

## Schedule 3

Size of the lot Number of bags (N)			Number of bags for sampling (n)	Quantity of the collected specimens (g)	Number of specimens*
	$\leq$	65	3	300 g ( 100 × 3 )	3
66	~	180	4	400 g ( 100 × 4 )	4
181	~	500	7	700 g ( 100 × 7 )	7
501	~	800	10	1,000 g ( 100 × 10 )	10
801	~	1,300	14	1,400 g ( 100 × 14 )	14
1,301	~	3,200	21	2,100 g ( 100 × 21 )	21
3,201	~	8,000	36	3,600 g ( 100 × 36 )	36
	$\geq$	8,001	52	5,200 g ( 100 × 52 )	52

\* If more than one specimen is taken, and any one of them exceeds the standard value, the inspected products are regarded as being in violation of the Act.